ADLER-WERK LACKFABRIK



To whom it may concern

ADLER-WERK Lackfabrik
Johann Berghofer GmbH & Co KG

A-6130 Schwaz Bergwerkstraße 22, PF 126

fon: +43 52 42 / 69 22 - 0 fax: +43 52 42 / 69 22 - 999 www.adler-lacke.com technical-support@adler-lacke.com

Schwaz, 10.08.2022 ZEwj, DW 717

Diisocyanates - Information

Dear Sir or Madam,

In August 2020, the restriction of diisocyanates was decided by Regulation (EU) 2020/1149. The restriction applies to diisocyanates per se, as well as to diisocyanates in mixtures from a concentration of more than 0.1 percent by weight.

From **24 August 2023**, diisocyanates above 0.1% by weight may only be manufactured, distributed and used if the required training of employees has taken place and is documented. Employers must keep records of the training of their employees. Refresher training is required every five years.

ADLER has therefore decided to convert all hardeners containing more than 0.1 per cent by weight of diisocyanates. The change will take place in the next few months. Informations on this matter will be available at ADLER website on time or from our Technical Field Service. Our customers do not have to complete any official training in order to be allowed to use our hardeners after 24 August 2023. ADLER therefore does not offer certified training for the use of hardeners containing more than 0.1 percent by weight of diisocyanates.

Best regards

Dr. Wilfrid Jochum

Wilfrid Jochum

System Management / Health, Safety and Environmental Management







